

10077978-050502

Client: GREENWALD & BASCH LLP
349 W. Commercial Street, Suite 2490
East Rochester, New York 14445-2403
TEL: 585-387-0280
FAX: 585-387-0288

Attorney: Duane C. Basch

Date Completed: April 12, 2002

Client Docket: BTI-16

Draftsman Docket: A2007DCB

Sheets: 58

Figures: 85




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11






FIG. 12



18077978.050502




FIG. 15




FIG. 16




FIG. 17




FIG. 18

12/58




FIG. 19




FIG. 20




FIG. 21

1007978-060502




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26

1007978-050502




FIG. 28

10077978.050502




FIG. 29




FIG. 30




FIG. 31




FIG. 32



FIG. 33




FIG. 34




FIG. 35

10077978.060506




FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40




FIG. 41

205090" 8262400T




FIG. 42




FIG. 43

10077978.050502




FIG. 44




FIG. 45




FIG. 46

1007978-060502




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51




FIG. 52




FIG. 53

205090" 8262200T




FIG. 54

40/58




FIG. 55




FIG. 56




FIG. 57

1007938.060502




FIG. 58




FIG. 59




FIG. 60

205090-8/6400T




FIG. 61




FIG. 62




FIG. 64






FIG. 65




FIG.66




FIG.67




FIG. 68




FIG. 69




FIG. 70

20250909 09:46:40

50/58




FIG. 71




FIG. 72

205090-846400T




FIG.73




FIG.74




FIG. 75




FIG. 76




FIG. 77




FIG. 78




FIG. 79




FIG.80




FIG.81

205090" 8/26/2001




FIG.82

57/58




FIG. 83




FIG. 84

205090-8/6/00T




FIG. 85